UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,744,409 B2 DATED : June 1, 2004 Page 1 of 1

DATED : June 1, 2004 INVENTOR(S) : Grant A. Ellis

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8,

Line 19, please add the following sentence after "... a single feed pin 200."

-- The feed pin 200 is connected between the top plate 100 and a first end of a short length of transmission line 300, similar to the transmission line 30 shown in Figures 1A and 3B. --

Column 9.

Line 8, "... shorting pins connecting..." should be -- ... shorting pins directly connecting... --

Line 17, change "... of claim 1, wherein..." to -- ... of claim 2, wherein... --

Signed and Sealed this

Sixteenth Day of November, 2004

VV. Judas

JON W. DUDAS

Director of the United States Patent and Trademark Office